# COMPLETION REPORT

| | | |
|---|---|---|
| 1 | Name of the work | Ward Maintenance of Desilting of drains, Tractor & JCB in Ward No: 13 in Shettyhalli Sub-Division |
| 2 | Sanctioned Estimate No. & Date | |
| 3 | Head of Account which is chargeable | |
| 4 | Instrument Order NO. & Date | |
| 5 | Name Of Contractor | Sri. R. Mangalaraju, No. 11/2, 3rd Stage, 3rd Block, Saneguruvanahalli, Basaveshwaranagar, Bangalore-560079. |
| 6 a | Time Stipulated for Completion of work | |
| b | Delay in Exculpation of Work | |
| 7 | Measurement recorded in | |
| 8 | Check Measurement of the Asst | |
| 9 | Name of the office/official in charge of the work | |
| 10 | a) Asst. Eng/junior Eng | |
| | b) Asst. Exe Engineer | |

| Sanctioned Estimate Amout | Amout Claims As per Actually Vide As per bills | Excess | Savings |
|---|---|---|---|
| | | | |

1) Certified that the above work has been completed within the stipulated time noted in the
2) Certified that the contractor has delayed and completed the work for which necessary fine recovered
3) Certified that the above work has been executed by the contractor satisfactory in

**ASSISTANT ENGINEER.**

**ASSIATANT EXECUTIVE ENGINEER**

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಎಸ್.ಎಂ ರಸ್ತೆ, ರವೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು